












The image contains six isometric drawings of mechanical assemblies, labeled A through F. Each drawing shows a different configuration of shafts, gears, and couplings. Assembly A shows a vertical shaft with a gear meshing with a horizontal shaft. Assembly B shows a horizontal shaft with a gear meshing with a vertical shaft. Assembly C shows a horizontal shaft with a gear meshing with a vertical shaft. Assembly D shows a horizontal shaft with a gear meshing with a vertical shaft. Assembly E shows a horizontal shaft with a gear meshing with a vertical shaft. Assembly F shows a horizontal shaft with a gear meshing with a vertical shaft.






3






P

P bar



T

°C



(3 bar)

Q

l/min.

